

Visual Problem Documentation

Location/Equipment Information

EXTERNAL ELEVATIONS

NORTH - EAST END

Asset ID: -

POOL

Buildings

Work Order#: NOT ISSUED

Page 11

Current Prob No: Visual/11

Is Chronic:

Operation Priority:

Critical to operation

Repair Priority: 1-Critical

Stroma Technology Ltd

Bradley Stoke Leisure Centre Swimming Pool

Fiddlers Wood Lane

Bradley Stoke, Bristol BS32

InspectionNo: 1488 Report Date: 02/02/2011

Classification:

Observations:


Decreased surface temperature at AR1 and AR2

What is the Cause: Suspected air leakage and thermal bridge from internal detail

Recommendations: Repair or replace seals and improve insulation

Estimated extra energy and CO2 per year for this anomaly (kWh/kg):

Estimated extra energy cost per year for this anomaly in £ GBP:





File: IR_1332A.JPG File: DC_1333.jpg

Date: 02/02/2011 Time: 10:22 AM Date: 02/02/2011 Time: 10:22 AM

Technician: Wallace, Richard Certification Level/No.: ITC Level II