



Visual Problem Documentation

Stroma Technology Ltd
Rushenden - 42 First Avenue

Location/Equipment Information
Asset ID: - INTERNAL ELEVATIONS HALLWAY

Work Order#: NOT ISSUED

Current Prob No: Visual/1	
Is Chronic:	Yes
Operation Priority:	Critical to operation
Repair Priority:	1-Critical

InspectionNo: 1982
Report Date: 21/12/2012

- Classification:** Buildings
- Observations:** Decreased temperature at AR1
- What is the Cause:** Suspected air leakage
- Recommendations:** Check seals and repair or replace where necessary



File: IR_3162a.jpg	Date: 21/12/2012	Time: 10:51 AM
File: DC_3163.jpg	Date: 21/12/2012	Time: 09:44 AM

Technician:	Wallace, Richard
Certification Level/No.:	ITC Level II